C O N V A I R A Division of General Dynamics Corporation (San Diego)

DESIGN INFORMATION BULLETIN

NO.: 26.003

CONVAIR REPORT NO. ZM-22-005


PAGE: 1 of 2

MODEL 22 AIRPLANE

CORONA DISCHARGE CONTROL

DATE: 8-14-57

H.F. ANTENNA SYSTEM



The above represents the minimum requirements for the control of corona discharge phenomenon in the immediate vicinity of the high frequency antenna isolation gap in the vertical stabilizer.

C O N V A I R A Division of General Dynamics Corporation (San Diego)

DESIGN INFORMATION BULLETIN

NO.: 26.003

CONVAIR REPORT NO. ZM-22-005

PAGE: 2 of 2

MODEL 22 AIRPLANE

DATE: 8-14-57

CORONA DISCHARGE CONTROL

H.F. ANTENNA SYSTEM

P. M. Keeler

Antenna Laboratory

A. J. Savard

Project Engineer

W. Garcia

Electronics Group

G. G.Green

Chief, Structures

J. Sikes

Wing & Tail Group